

Photo Log

Mark Ford Training Center

by Andreescu, Stephanie

CWA Section 404 Inspection: September 22, 2016



P9220029 – Overview of Site, Taken from Barn Area



P9220030 – Overview of Site, Taken from Barn Area



P9220031 – Looking Upstream from Property Edge



P9220032 – Looking Downstream from Property Edge



P9220033 – Under North Bridge, Looking Downstream



P9220034 – Inside of Track, Looking Downstream



P9220035 – Inside of Track, Looking Upstream



P9220036 – Under South Bridge, Looking Downstream



P9220037 – Stream Inside Track, Facing Pond



P9220038 – Straightened Stream, Facing Downstream from Outside Edge of Track



P9220039 – Straightened Stream, Facing Downstream



P9220040 – *Schoenoplectus* spp., riparian vegetation along straightened stream



P9220041 – Straightened Stream, Looking Upstream from Small Bridge



P9220042 – Straightened Stream, Looking Downstream from Small Bridge